

**United States Environmental Protection Agency  
Criminal Investigation Division  
Investigative Activity Report**

**Case Number**

0411-0040

**Case Title:**

Boyle Skene Water Corporation

**Reporting Office:**

Gulf Breeze, FL, Resident Office

**Subject of Report:**

Interview of (b) (6), (b) (7) on July 29, 2015

**Activity Date:**

July 29, 2015

**Reporting Official and Date:**

(b) (6), (b) (7)(C)

(b) (6), (b) (7)

**Approving Official and Date:**

(b) (6), (b) (7)

Acting (b) (6), (b) (7)(C)

*Resident Agent in Charge*

30-JUL-2015, Signed by: (b) (6), (b) (7)

30-JUL-2015, Approved by: (b) (6), (b) (7)

**SYNOPSIS**

On July 29, 2015, (b) (6), (b) (7) interviewed (b) (6), (b) (7)(C), (b) (6), (b) (7)(C) for Boyle Skene Water Corporation (BSWC), at BSWC's offices in Cleveland, MS. (b) (6), (b) (7) witnessed (b) (6), (b) (7)(C) in the area of a damaged water line on four occasions and captured (b) (6), (b) (7) on camera on a fifth occasion.

**DETAILS**

On July 29, 2015, (b) (6), (b) (7) (b) (6), (b) (6), EPA-CID, interviewed (b) (6), (b) (7)(C) (b) (6), (b) (7)(C) for Boyle Skene Water Corporation (BSWC), at BSWC's offices in Cleveland, MS. (b) (6), (b) (7) identified himself and explained the purpose of the interview.

(b) (6), (b) (7) has been a licensed plumber for approximately eleven years. (b) (6), (b) (7) was hired by BSWC in (b) (6), (b) (7). Prior to that, (b) (6), (b) (7) owned and operated his own plumbing business, McIntyre Plumbing. (b) (6), (b) (7) did not know (b) (6), (b) (7)(C), the subject of this investigation, very well before (b) (6), (b) (7) started working for BSWC. (b) (6), (b) (7) could put a face with the name and could pick (b) (6), (b) (7) out of a lineup. (b) (6), (b) (7) knew who (b) (6), (b) (7) was but they did not have a personal relationship. Some of (b) (6), (b) (7) relatives go to the same church as (b) (6), (b) (7). Also, (b) (6), (b) (7) did the plumbing in (b) (6), (b) (7) daughter's house and (b) (6), (b) (7) was the one that paid for the work.

The first incident of water line tampering that (b) (6), (b) (7) responded to as an employee of BSWC was on July 31, 2014. (b) (6), (b) (7) had received the call about the water outage early that morning. A water line was damaged at a meter near an airstrip off Highway 448. Mississippi Bureau of Investigations Investigator (b) (6), (b) (7) also responded to the incident. (b) (6), (b) (7) recalled that (b) (6), (b) (7) drove by twice that morning while (b) (6), (b) (7) was capping off the water line. The first time (b) (6), (b) (7) saw (b) (6), (b) (7)(C) was traveling west on highway 448 in (b) (6), (b) (7) black pickup truck. (b) (6), (b) (7) later witnessed (b) (6), (b) (7) drive by traveling east on highway 448. (b) (6), (b) (7) left the site after (b) (6), (b) (7) drove by the second time. (b) (6), (b) (7) also traveled east on highway 448.

The second incident of water line tampering when (b) (6), (b) (7) witnessed (b) (6), (b) (7) in the area was on November 9, 2014 when a water line on White Star Road was damaged. (b) (6), (b) (7) recalled that he received the call about the leak in the early to mid-morning on a Sunday because (b) (6), (b) (7) had to miss church that morning. During that incident (b) (6), (b) (7) discovered that a bleed-off valve had been damaged. (b) (6), (b) (7) was at the incident site and had located the leak. (b) (6), (b) (7) was about to head into town to pick up parts to repair the leak when (b) (6), (b) (7)

This document contains neither recommendations nor conclusions of the EPA.  
It is the property of the EPA and is loaned to your agency;  
it and its contents are not to be distributed outside your agency.

**United States Environmental Protection Agency  
Criminal Investigation Division  
Investigative Activity Report**

**Case Number**

0411-0040

witnessed (b) (6), (b) drive by in (b) (6), (b) black pickup truck. (b) (6), (b) was traveling on White Star Road which is a gravel country road. White Star Road is not a direct route for (b) (6), (b) to travel to Cleveland or any notable town. (b) (6), (b) observed that (b) (6), (b) had a "smile or smirk" on his face as he drove by. (b) (6), (b) (7) did not get the leak repaired until between noon and two in the afternoon. (b) (6), (b) also repaired a water line that had been tampered with at Old Ruleville Road the same evening.

The third incident of water line tampering when (b) (6), (b) witnessed (b) (6), (b) in the area was on November 10, 2014 when a water line at the intersection of Smith and Park Streets was damaged. On the morning of November 10, 2014, (b) (6), (b) repaired a water line that had been tampered with on Herbison Road. A bleed-off valve had been damaged. While (b) (6), (b) was repairing the Herbison Road leak, (b) (6), (b) received a call about another leak at the intersection of Smith and Park Streets. (b) (6), (b) (7)(C) were all present at the Smith and Park leak. (b) (6), (b) had repaired the leak and placed the trackhoe back on the trailer. (b) (6), (b) was walking to his truck preparing to drive to a bleed-off valve and turn the water back on when he witnessed (b) (6), (b) drive by heading north on Smith Street. (b) (6), (b) was driving a black truck and no one was with him at the time.

(b) (6), (b) pulled out behind (b) (6), (b) heading the same direction toward the bleed-off valve. (b) (6), (b) turned on Buckley Jones Road and so did (b) (6), (b) (7) because that was the way he needed to go to get to the bleed-off valve. (b) (6), (b) pulled off into a driveway and (b) (6), (b) kept going. (b) (6), (b) pulled into the driveway of (b) (6), (b) (7)(C) when he noticed that blue marking paint was spraying all over the bed of his truck. (b) (6), (b) got out of the truck to stop the paint spraying. (b) (6), (b) driveway happened to be approximately three houses down from where (b) (6), (b) had stopped. After (b) (6), (b) stopped the paint, he called (b) (6), (b) and told her that he had to head into Cleveland immediately so he could go to a car wash and rinse the paint out of his truck. As (b) (6), (b) (7) was pulling out, (b) (6), (b) drove past first. (b) (6), (b) pulled out behind (b) (6), (b) and had to follow (b) (6), (b) all the way into Cleveland because (b) (6), (b) happened to be going in the same direction. When (b) (6), (b) got to the car wash, (b) (6), (b) pulled in to his intended destination. (b) (6), (b) continued traveling down the highway. Because (b) (6), (b) (7) followed (b) (6), (b) into Cleveland on November 10, 2014, (b) (6), (b) filed a police report charging (b) (6), (b) with stalking. (b) (6), (b) (7) was arrested on November 14, 2014.

The fourth incident of water line tampering when (b) (6), (b) witnessed (b) (6), (b) in the area was on January 8, 2015 when a water line on Highway 446 was damaged. (b) (6), (b) (7)(C) were all at the repair site. BSWC employee (b) (6), (b) (7) may have also been present. (b) (6), (b) (7) was either operating the trackhoe or was down in the hole working when (b) (6), (b) witnessed (b) (6), (b) drive by in a black truck heading from east to west on Highway 446. (b) (6), (b) thinks that a female passenger was with (b) (6), (b) at the time. (b) (6), (b) (7) recalled that the incident occurred during daylight hours and (b) (6), (b) (7) was able to see (b) (6), (b) face and confirm that it was in fact (b) (6), (b). (b) (6), (b) thinks that (b) (6), (b) took a cell phone video of (b) (6), (b) driving past the repair location.

The fifth incident when (b) (6), (b) was witnessed in the area of a damaged water line was on January 15, 2015 near Evans Road. On January 14, 2015, (b) (6), (b) had to repair a water line that had been tampered with on Evans Road. Before (b) (6), (b) left the site, (b) (6), (b) deployed a game camera facing the road that runs adjacent to the water line. (b) (6), (b) had just

This document contains neither recommendations nor conclusions of the EPA.  
It is the property of the EPA and is loaned to your agency;  
it and its contents are not to be distributed outside your agency.

**United States Environmental Protection Agency  
Criminal Investigation Division  
Investigative Activity Report**

**Case Number**

0411-0040

gotten the camera and he did not set the date and time correctly on the camera. On January 15, 2015, the camera captured photos of (b) (6), (b) (6) black truck stopping at the location of the previous day's water line repair. (b) (6), (b) (6) truck appeared to pull up, back up, and pull up again.

This document contains neither recommendations nor conclusions of the EPA.  
It is the property of the EPA and is loaned to your agency;  
it and its contents are not to be distributed outside your agency.